

---

# Condition Report

Inspected on May 11, 2020 3:32 PM

| Report Created on May 11, 2020 5:24 PM

---


## Entry

| Items               | Values                 | Notes                 |
|---------------------|------------------------|-----------------------|
| Door(s)             | All Good: Yes          | Some scuffs and dents |
| Floor               | All Good: Yes          |                       |
| Ceiling             | All Good: Yes          |                       |
| Smoke / CO detector | Condition: Not present |                       |
| Walls               | All Good: Yes          |                       |


## Photos



Overview Photos  
05/11/2020 4:33 PM



Door(s) (1/7)  
05/11/2020 4:33 PM




Door(s) (2/7)  
05/11/2020 4:33 PM



Door(s) (3/7)  
05/11/2020 4:34 PM




Door(s) (4/7)  
05/11/2020 4:34 PM



Door(s) (5/7)  
05/11/2020 4:34 PM



Door(s) (6/7)  
05/11/2020 4:34 PM



Door(s) (7/7)  
05/11/2020 4:34 PM




Floor (1/2)  
05/11/2020 4:35 PM



Floor (2/2)  
05/11/2020 4:35 PM



Ceiling  
05/11/2020 4:36 PM




Walls (1/7)  
05/11/2020 4:37 PM




Walls (2/7)  
05/11/2020 4:37 PM



Walls (3/7)  
05/11/2020 4:37 PM



Walls (4/7)  
05/11/2020 4:37 PM



Walls (5/7)  
05/11/2020 4:37 PM



Walls (6/7)  
05/11/2020 4:37 PM



Walls (7/7)  
05/11/2020 4:37 PM

## Hallway/Stairs

| Items                    | Values                 | Notes           |
|--------------------------|------------------------|-----------------|
| Walls / Windows / Blinds | All Good: Yes          | A little dirty  |
| Floor                    | All Good: Yes          |                 |
| Ceiling                  | All Good: Yes          | Light burnt out |
| Smoke / CO detector      | Condition: Not present |                 |

## Photos




Overview Photos (1/2)  
05/11/2020 5:11 PM



Overview Photos (2/2)  
05/11/2020 5:11 PM



Walls / Windows / Blinds (1/6)  
05/11/2020 5:11 PM




Walls / Windows / Blinds (2/6)  
05/11/2020 5:12 PM



Walls / Windows / Blinds (3/6)  
05/11/2020 5:12 PM




Walls / Windows / Blinds (4/6)  
05/11/2020 5:12 PM



Walls / Windows / Blinds (5/6)  
05/11/2020 5:12 PM



Walls / Windows / Blinds (6/6)  
05/11/2020 5:12 PM



Floor (1/3)  
05/11/2020 5:12 PM



Floor (2/3)  
05/11/2020 5:12 PM



Floor (3/3)  
05/11/2020 5:12 PM



Ceiling (1/2)  
05/11/2020 5:12 PM



Ceiling (2/2)  
05/11/2020 5:13 PM

## Living/Dining Room

| Items                    | Values                        | Notes                                                                                               |
|--------------------------|-------------------------------|-----------------------------------------------------------------------------------------------------|
| Door(s)                  | All Good: Yes                 |                                                                                                     |
| Walls / Windows / Blinds | All Good: Yes                 | The blinds on left are a little older and dirtier then the new ones in right. Both fully functional |
| Windows Screens          | Condition: Present, no issues |                                                                                                     |
| Floor                    | All Good: Yes                 | Some wear and shiny tape in areas                                                                   |
| Ceiling                  | All Good: Yes                 |                                                                                                     |
| Smoke / CO detector      | Condition: Present            |                                                                                                     |
| Closet / Cupboards / etc | All Good: Yes                 |                                                                                                     |




## Photos



Overview Photos (1/5)  
05/11/2020 4:38 PM



Overview Photos (2/5)  
05/11/2020 4:39 PM



Overview Photos (3/5)  
05/11/2020 4:39 PM



Overview Photos (4/5)  
05/11/2020 4:39 PM



Overview Photos (5/5)  
05/11/2020 4:39 PM



Door(s) (1/2)  
05/11/2020 4:40 PM




Door(s) (2/2)  
05/11/2020 4:40 PM




Walls / Windows / Blinds (1/14)  
05/11/2020 4:41 PM



Walls / Windows / Blinds (2/14)  
05/11/2020 4:42 PM



Walls / Windows / Blinds (3/14)  
05/11/2020 4:42 PM



Walls / Windows / Blinds (4/14)  
05/11/2020 4:42 PM



Walls / Windows / Blinds (5/14)  
05/11/2020 4:42 PM



Walls / Windows / Blinds (6/14)  
05/11/2020 4:43 PM



Walls / Windows / Blinds (7/14)  
05/11/2020 4:43 PM



Walls / Windows / Blinds (8/14)  
05/11/2020 4:43 PM



Walls / Windows / Blinds (9/14)  
05/11/2020 4:44 PM



Walls / Windows / Blinds (10/14)  
05/11/2020 4:44 PM



Walls / Windows / Blinds (11/14)  
05/11/2020 4:44 PM



Walls / Windows / Blinds (12/14)  
05/11/2020 4:44 PM



Walls / Windows / Blinds (13/14)  
05/11/2020 4:44 PM



Walls / Windows / Blinds (14/14)  
05/11/2020 4:44 PM



Floor (1/5)  
05/11/2020 4:46 PM



Floor (2/5)  
05/11/2020 4:46 PM



Floor (3/5)  
05/11/2020 4:46 PM



Floor (4/5)  
05/11/2020 4:46 PM



Floor (5/5)  
05/11/2020 4:47 PM



Ceiling (1/6)  
05/11/2020 4:47 PM



Ceiling (2/6)  
05/11/2020 4:47 PM



Ceiling (3/6)  
05/11/2020 4:47 PM



Ceiling (4/6)  
05/11/2020 4:47 PM



Ceiling (5/6)  
05/11/2020 4:47 PM



Ceiling (6/6)  
05/11/2020 4:48 PM



Smoke / CO detector  
05/11/2020 4:41 PM



Closet / Cupboards / etc  
05/11/2020 4:41 PM

# Kitchen

| Items                        | Values                       | Notes                                         |
|------------------------------|------------------------------|-----------------------------------------------|
| Door(s)                      | All Good: Yes                | Locks and closes good                         |
| Walls / Windows / Blinds     | All Good: Yes                | Need to be cleaned                            |
| Windows Screens              | Condition: Present, issue(s) | Hole in screen near handle                    |
| Floor                        | All Good: Yes                |                                               |
| Ceiling                      | All Good: Yes                | One light bulb burnt out                      |
| Smoke / CO detector          | Condition: Not present       |                                               |
| Closet / Cupboards / etc     | All Good: Yes                |                                               |
| Closet / Cupboards / etc (2) | All Good: Yes                |                                               |
| Counter Tops                 | All Good: Yes                |                                               |
| Sink & Underneath Sink       | All Good: Yes                |                                               |
| Refrigerator                 | All Good: Yes                |                                               |
| Oven /Stove / Range          | All Good: Yes                |                                               |
| Microwave                    | All Good: Yes                | Some minor cracks in plastic of door and hood |
| Dishwasher                   | All Good: Yes                |                                               |
| Cupboards (3)                | All Good: Yes                |                                               |



## Photos



Overview Photos (1/6)  
05/11/2020 4:48 PM



Overview Photos (2/6)  
05/11/2020 4:48 PM



Overview Photos (3/6)  
05/11/2020 4:49 PM



Overview Photos (4/6)  
05/11/2020 4:49 PM



Overview Photos (5/6)  
05/11/2020 4:49 PM




Overview Photos (6/6)  
05/11/2020 4:49 PM




Door(s) (1/5)  
05/11/2020 4:49 PM



Door(s) (2/5)  
05/11/2020 4:49 PM



Door(s) (3/5)  
05/11/2020 4:50 PM



Door(s) (4/5)  
05/11/2020 4:50 PM




Door(s) (5/5)  
05/11/2020 4:50 PM




Walls / Windows / Blinds (1/16)  
05/11/2020 4:50 PM




Walls / Windows / Blinds (2/16)  
05/11/2020 4:50 PM



Walls / Windows / Blinds (3/16)  
05/11/2020 4:51 PM



Walls / Windows / Blinds (4/16)  
05/11/2020 4:51 PM



Walls / Windows / Blinds (5/16)  
05/11/2020 4:51 PM





Walls / Windows / Blinds (6/16)  
05/11/2020 4:51 PM



Walls / Windows / Blinds (7/16)  
05/11/2020 4:51 PM



Walls / Windows / Blinds (8/16)  
05/11/2020 4:51 PM



Walls / Windows / Blinds (9/16)  
05/11/2020 4:51 PM



Walls / Windows / Blinds (10/16)  
05/11/2020 4:51 PM



Walls / Windows / Blinds (11/16)  
05/11/2020 4:52 PM




Walls / Windows / Blinds (12/16)  
05/11/2020 4:52 PM



Walls / Windows / Blinds (13/16)  
05/11/2020 4:52 PM



Walls / Windows / Blinds (14/16)  
05/11/2020 4:52 PM



Walls / Windows / Blinds (15/16)  
05/11/2020 4:52 PM



Walls / Windows / Blinds (16/16)  
05/11/2020 4:53 PM



Windows Screens (1/2)  
05/11/2020 4:53 PM



Windows Screens (2/2)  
05/11/2020 4:54 PM



Floor (1/4)  
05/11/2020 4:54 PM



Floor (2/4)  
05/11/2020 4:55 PM




Floor (3/4)  
05/11/2020 4:55 PM



Floor (4/4)  
05/11/2020 4:55 PM



Ceiling (1/4)  
05/11/2020 4:55 PM



Ceiling (2/4)  
05/11/2020 4:55 PM



Ceiling (3/4)  
05/11/2020 4:55 PM





Ceiling (4/4)  
05/11/2020 4:55 PM



Closet / Cupboards / etc (1/16)  
05/11/2020 4:56 PM



Closet / Cupboards / etc (2/16)  
05/11/2020 4:56 PM



Closet / Cupboards / etc (3/16)  
05/11/2020 4:56 PM



Closet / Cupboards / etc (4/16)  
05/11/2020 4:56 PM



Closet / Cupboards / etc (5/16)  
05/11/2020 4:56 PM



Closet / Cupboards / etc (6/16)  
05/11/2020 4:56 PM



Closet / Cupboards / etc (7/16)  
05/11/2020 4:57 PM



Closet / Cupboards / etc (8/16)  
05/11/2020 4:57 PM



Closet / Cupboards / etc (9/16)  
05/11/2020 4:57 PM



Closet / Cupboards / etc (10/16)  
05/11/2020 4:57 PM



Closet / Cupboards / etc (11/16)  
05/11/2020 4:57 PM



Closet / Cupboards / etc (12/16)  
05/11/2020 4:57 PM



Closet / Cupboards / etc (13/16)  
05/11/2020 4:57 PM



Closet / Cupboards / etc (14/16)  
05/11/2020 4:58 PM



Closet / Cupboards / etc (15/16)  
05/11/2020 4:58 PM



Closet / Cupboards / etc (16/16)  
05/11/2020 4:58 PM



Closet / Cupboards / etc (2) (1/16)  
05/11/2020 4:58 PM



Closet / Cupboards / etc (2) (2/16)  
05/11/2020 4:58 PM



Closet / Cupboards / etc (2) (3/16)  
05/11/2020 4:59 PM





Closet / Cupboards / etc (2) (4/16)  
05/11/2020 4:59 PM



Closet / Cupboards / etc (2) (5/16)  
05/11/2020 4:59 PM



Closet / Cupboards / etc (2) (6/16)  
05/11/2020 4:59 PM



Closet / Cupboards / etc (2) (7/16)  
05/11/2020 4:59 PM



Closet / Cupboards / etc (2) (8/16)  
05/11/2020 4:59 PM



Closet / Cupboards / etc (2) (9/16)  
05/11/2020 4:59 PM



Closet / Cupboards / etc (2) (10/16)  
05/11/2020 4:59 PM



Closet / Cupboards / etc (2) (11/16)  
05/11/2020 4:59 PM



Closet / Cupboards / etc (2) (12/16)  
05/11/2020 5:00 PM



Closet / Cupboards / etc (2) (13/16)  
05/11/2020 5:00 PM



Closet / Cupboards / etc (2) (14/16)  
05/11/2020 5:00 PM



Closet / Cupboards / etc (2) (15/16)  
05/11/2020 5:00 PM



Closet / Cupboards / etc (2) (16/16)  
05/11/2020 5:00 PM



Counter Tops (1/6)  
05/11/2020 5:01 PM



Counter Tops (2/6)  
05/11/2020 5:01 PM



Counter Tops (3/6)  
05/11/2020 5:01 PM



Counter Tops (4/6)  
05/11/2020 5:01 PM



Counter Tops (5/6)  
05/11/2020 5:01 PM



Counter Tops (6/6)  
05/11/2020 5:02 PM



Sink & Underneath Sink (1/4)  
05/11/2020 5:02 PM





Sink & Underneath Sink (2/4)  
05/11/2020 5:02 PM



Sink & Underneath Sink (3/4)  
05/11/2020 5:02 PM



Sink & Underneath Sink (4/4)  
05/11/2020 5:02 PM



Refrigerator (1/10)  
05/11/2020 5:02 PM



Refrigerator (2/10)  
05/11/2020 5:03 PM




Refrigerator (3/10)  
05/11/2020 5:03 PM



Refrigerator (4/10)  
05/11/2020 5:03 PM



Refrigerator (5/10)  
05/11/2020 5:03 PM



Refrigerator (6/10)  
05/11/2020 5:03 PM



Refrigerator (7/10)  
05/11/2020 5:03 PM



Refrigerator (8/10)  
05/11/2020 5:03 PM



Refrigerator (9/10)  
05/11/2020 5:03 PM



Refrigerator (10/10)  
05/11/2020 5:04 PM



Oven /Stove / Range (1/5)  
05/11/2020 5:04 PM



Oven /Stove / Range (2/5)  
05/11/2020 5:04 PM



Oven /Stove / Range (3/5)  
05/11/2020 5:04 PM



Oven /Stove / Range (4/5)  
05/11/2020 5:04 PM



Oven /Stove / Range (5/5)  
05/11/2020 5:05 PM



Microwave (1/5)  
05/11/2020 5:05 PM



Microwave (2/5)  
05/11/2020 5:05 PM





Microwave (3/5)  
05/11/2020 5:05 PM



Microwave (4/5)  
05/11/2020 5:05 PM



Microwave (5/5)  
05/11/2020 5:05 PM



Dishwasher (1/4)  
05/11/2020 5:05 PM



Dishwasher (2/4)  
05/11/2020 5:06 PM



Dishwasher (3/4)  
05/11/2020 5:06 PM



Dishwasher (4/4)  
05/11/2020 5:06 PM



Cupboards (3) (1/8)  
05/11/2020 5:00 PM



Cupboards (3) (2/8)  
05/11/2020 5:01 PM



Cupboards (3) (3/8)  
05/11/2020 5:01 PM



Cupboards (3) (4/8)  
05/11/2020 5:01 PM



Cupboards (3) (5/8)  
05/11/2020 5:06 PM



Cupboards (3) (6/8)  
05/11/2020 5:07 PM



Cupboards (3) (7/8)  
05/11/2020 5:07 PM



Cupboards (3) (8/8)  
05/11/2020 5:07 PM

# Bathroom


| Items   | Values        | Notes |
|---------|---------------|-------|
| Door(s) | All Good: Yes |       |

| Items                    | Values        | Notes               |
|--------------------------|---------------|---------------------|
| Walls / Windows / Blinds | All Good: Yes | Some chips in paint |
| Floor                    | All Good: Yes |                     |
| Ceiling                  | All Good: Yes |                     |
| Closet / Cupboards / etc | All Good: Yes |                     |
| Counter Tops             | All Good: Yes |                     |
| Sink & Underneath Sink   | All Good: Yes |                     |
| Toilet                   | All Good: Yes |                     |


## Photos




Overview Photos (1/3)  
05/11/2020 5:07 PM



Overview Photos (2/3)  
05/11/2020 5:07 PM




Overview Photos (3/3)  
05/11/2020 5:07 PM




Door(s) (1/4)  
05/11/2020 5:08 PM



Door(s) (2/4)  
05/11/2020 5:08 PM




Door(s) (3/4)  
05/11/2020 5:08 PM




Door(s) (4/4)  
05/11/2020 5:08 PM



Walls / Windows / Blinds (1/9)  
05/11/2020 5:08 PM



Walls / Windows / Blinds (2/9)  
05/11/2020 5:08 PM



Walls / Windows / Blinds (3/9)  
05/11/2020 5:08 PM



Walls / Windows / Blinds (4/9)  
05/11/2020 5:08 PM




Walls / Windows / Blinds (5/9)  
05/11/2020 5:08 PM






Walls / Windows / Blinds (6/9)  
05/11/2020 5:09 PM



Walls / Windows / Blinds (7/9)  
05/11/2020 5:09 PM



Walls / Windows / Blinds (8/9)  
05/11/2020 5:09 PM



Walls / Windows / Blinds (9/9)  
05/11/2020 5:09 PM



Floor (1/4)  
05/11/2020 5:09 PM



Floor (2/4)  
05/11/2020 5:09 PM



Floor (3/4)  
05/11/2020 5:09 PM



Floor (4/4)  
05/11/2020 5:10 PM



Ceiling (1/4)  
05/11/2020 5:10 PM



Ceiling (2/4)  
05/11/2020 5:10 PM



Ceiling (3/4)  
05/11/2020 5:10 PM



Ceiling (4/4)  
05/11/2020 5:10 PM



Closet / Cupboards / etc  
05/11/2020 5:10 PM



Counter Tops  
05/11/2020 5:10 PM



Sink & Underneath Sink (1/2)  
05/11/2020 5:10 PM



Sink & Underneath Sink (2/2)  
05/11/2020 5:10 PM



Toilet (1/3)  
05/11/2020 5:11 PM



Toilet (2/3)  
05/11/2020 5:11 PM



Toilet (3/3)  
05/11/2020 5:11 PM

## Bathroom 2

| Items                    | Values        | Notes |
|--------------------------|---------------|-------|
| Door(s)                  | All Good: Yes |       |
| Walls / Windows / Blinds | All Good: Yes |       |
| Floor                    | All Good: Yes |       |
| Ceiling                  | All Good: Yes |       |
| Closet / Cupboards / etc | All Good: Yes |       |
| Counter Tops             | All Good: Yes |       |
| Sink & Underneath Sink   | All Good: Yes |       |
| Shower / Tub             | All Good: Yes |       |
| Toilet                   | All Good: Yes |       |


## Photos




Overview Photos (1/2)  
05/11/2020 5:31 PM



Overview Photos (2/2)  
05/11/2020 5:31 PM




Door(s) (1/5)  
05/11/2020 5:31 PM




Door(s) (2/5)  
05/11/2020 5:31 PM



Door(s) (3/5)  
05/11/2020 5:31 PM



Door(s) (4/5)  
05/11/2020 5:31 PM



Door(s) (5/5)  
05/11/2020 5:31 PM



Walls / Windows / Blinds (1/6)  
05/11/2020 5:32 PM





Walls / Windows / Blinds (2/6)  
05/11/2020 5:32 PM



Walls / Windows / Blinds (3/6)  
05/11/2020 5:32 PM



Walls / Windows / Blinds (4/6)  
05/11/2020 5:32 PM



Walls / Windows / Blinds (5/6)  
05/11/2020 5:32 PM




Walls / Windows / Blinds (6/6)  
05/11/2020 5:32 PM



Floor (1/4)  
05/11/2020 5:32 PM



Floor (2/4)  
05/11/2020 5:32 PM



Floor (3/4)  
05/11/2020 5:32 PM



Floor (4/4)  
05/11/2020 5:32 PM



Ceiling (1/2)  
05/11/2020 5:33 PM



Ceiling (2/2)  
05/11/2020 5:33 PM



Closet / Cupboards / etc (1/3)  
05/11/2020 5:33 PM



Closet / Cupboards / etc (2/3)  
05/11/2020 5:33 PM



Closet / Cupboards / etc (3/3)  
05/11/2020 5:33 PM



Counter Tops  
05/11/2020 5:33 PM



Sink & Underneath Sink (1/3)  
05/11/2020 5:33 PM




Sink & Underneath Sink (2/3)  
05/11/2020 5:34 PM



Sink & Underneath Sink (3/3)  
05/11/2020 5:34 PM



Shower / Tub (1/4)  
05/11/2020 5:34 PM



Shower / Tub (2/4)  
05/11/2020 5:34 PM



Shower / Tub (3/4)  
05/11/2020 5:34 PM



Shower / Tub (4/4)  
05/11/2020 5:34 PM



Toilet (1/2)  
05/11/2020 5:34 PM



Toilet (2/2)  
05/11/2020 5:34 PM

### Bathroom 3


| Items                    | Values        | Notes                   |
|--------------------------|---------------|-------------------------|
| Door(s)                  | All Good: Yes |                         |
| Walls / Windows / Blinds | All Good: Yes | Some peeling above tile |
| Floor                    | All Good: Yes |                         |
| Ceiling                  | All Good: Yes |                         |
| Closet / Cupboards / etc | All Good: Yes |                         |
| Counter Tops             | All Good: Yes |                         |
| Sink & Underneath Sink   | All Good: Yes |                         |
| Shower / Tub             | All Good: Yes |                         |
| Toilet                   | All Good: Yes |                         |




## Photos




Overview Photos  
05/11/2020 5:35 PM




Door(s) (1/4)  
05/11/2020 5:35 PM




Door(s) (2/4)  
05/11/2020 5:35 PM



Door(s) (3/4)  
05/11/2020 5:35 PM



Door(s) (4/4)  
05/11/2020 5:35 PM



Walls / Windows / Blinds (1/6)  
05/11/2020 5:36 PM



Walls / Windows / Blinds (2/6)  
05/11/2020 5:36 PM



Walls / Windows / Blinds (3/6)  
05/11/2020 5:36 PM



Walls / Windows / Blinds (4/6)  
05/11/2020 5:36 PM




Walls / Windows / Blinds (5/6)  
05/11/2020 5:36 PM




Walls / Windows / Blinds (6/6)  
05/11/2020 5:36 PM




Floor (1/5)  
05/11/2020 5:36 PM



Floor (2/5)  
05/11/2020 5:36 PM



Floor (3/5)  
05/11/2020 5:36 PM



Floor (4/5)  
05/11/2020 5:36 PM



Floor (5/5)  
05/11/2020 5:36 PM



Ceiling (1/2)  
05/11/2020 5:37 PM



Ceiling (2/2)  
05/11/2020 5:37 PM



Closet / Cupboards / etc (1/3)  
05/11/2020 5:37 PM



Closet / Cupboards / etc (2/3)  
05/11/2020 5:37 PM




Closet / Cupboards / etc (3/3)  
05/11/2020 5:37 PM



Counter Tops  
05/11/2020 5:37 PM



Sink & Underneath Sink (1/3)  
05/11/2020 5:37 PM



Sink & Underneath Sink (2/3)  
05/11/2020 5:37 PM



Sink & Underneath Sink (3/3)  
05/11/2020 5:37 PM



Shower / Tub (1/5)  
05/11/2020 5:37 PM



Shower / Tub (2/5)  
05/11/2020 5:37 PM



Shower / Tub (3/5)  
05/11/2020 5:38 PM



Shower / Tub (4/5)  
05/11/2020 5:38 PM



Shower / Tub (5/5)  
05/11/2020 5:38 PM



Toilet (1/2)  
05/11/2020 5:38 PM



Toilet (2/2)  
05/11/2020 5:38 PM

# Bedroom

| Items   | Values        | Notes |
|---------|---------------|-------|
| Door(s) | All Good: Yes |       |



| Items                    | Values                        | Notes                    |
|--------------------------|-------------------------------|--------------------------|
| Walls / Windows / Blinds | All Good: Yes                 | Walls are a little dirty |
| Windows Screens          | Condition: Present, no issues |                          |
| Floor                    | All Good: Yes                 |                          |
| Ceiling                  | All Good: Yes                 |                          |
| Closet / Cupboards / etc | All Good: Yes                 |                          |
| Smoke / CO detector      | Condition: Present            | Needs to be hung         |

## Photos



Overview Photos (1/4)  
05/11/2020 5:13 PM




Overview Photos (2/4)  
05/11/2020 5:13 PM




Overview Photos (3/4)  
05/11/2020 5:13 PM



Overview Photos (4/4)  
05/11/2020 5:13 PM



Door(s) (1/3)  
05/11/2020 5:14 PM



Door(s) (2/3)  
05/11/2020 5:14 PM



Door(s) (3/3)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (1/10)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (2/10)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (3/10)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (4/10)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (5/10)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (6/10)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (7/10)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (8/10)  
05/11/2020 5:14 PM



Walls / Windows / Blinds (9/10)  
05/11/2020 5:15 PM



Walls / Windows / Blinds (10/10)  
05/11/2020 5:15 PM



Floor (1/4)  
05/11/2020 5:15 PM



Floor (2/4)  
05/11/2020 5:15 PM



Floor (3/4)  
05/11/2020 5:15 PM




Floor (4/4)  
05/11/2020 5:15 PM



Ceiling (1/4)  
05/11/2020 5:16 PM



Ceiling (2/4)  
05/11/2020 5:16 PM



Ceiling (3/4)  
05/11/2020 5:16 PM



Ceiling (4/4)  
05/11/2020 5:16 PM



Closet / Cupboards / etc (1/5)  
05/11/2020 5:16 PM




Closet / Cupboards / etc (2/5)  
05/11/2020 5:16 PM



Closet / Cupboards / etc (3/5)  
05/11/2020 5:16 PM



Closet / Cupboards / etc (4/5)  
05/11/2020 5:16 PM



Closet / Cupboards / etc (5/5)  
05/11/2020 5:16 PM



Smoke / CO detector  
05/11/2020 5:16 PM



## Bedroom 2

| Items                    | Values                        | Notes                          |
|--------------------------|-------------------------------|--------------------------------|
| Door(s)                  | All Good: Yes                 |                                |
| Walls / Windows / Blinds | All Good: Yes                 |                                |
| Windows Screens          | Condition: Present, no issues |                                |
| Floor                    | All Good: No                  | Small tear in carpet near door |
| Ceiling                  | All Good: Yes                 |                                |
| Closet / Cupboards / etc | All Good: Yes                 | Light cover missing            |
| Smoke / CO detector      | Condition: Present            | Needs to be rehung             |

## Photos



Overview Photos (1/4)  
05/11/2020 5:23 PM




Overview Photos (2/4)  
05/11/2020 5:23 PM




Overview Photos (3/4)  
05/11/2020 5:23 PM




Overview Photos (4/4)  
05/11/2020 5:23 PM




Door(s) (1/3)  
05/11/2020 5:23 PM




Door(s) (2/3)  
05/11/2020 5:23 PM



Door(s) (3/3)  
05/11/2020 5:23 PM



Walls / Windows / Blinds (1/8)  
05/11/2020 5:24 PM



Walls / Windows / Blinds (2/8)  
05/11/2020 5:24 PM



Walls / Windows / Blinds (3/8)  
05/11/2020 5:24 PM



Walls / Windows / Blinds (4/8)  
05/11/2020 5:24 PM



Walls / Windows / Blinds (5/8)  
05/11/2020 5:24 PM



Walls / Windows / Blinds (6/8)  
05/11/2020 5:24 PM



Walls / Windows / Blinds (7/8)  
05/11/2020 5:24 PM



Walls / Windows / Blinds (8/8)  
05/11/2020 5:24 PM



Floor (1/6)  
05/11/2020 5:24 PM



Floor (2/6)  
05/11/2020 5:24 PM



Floor (3/6)  
05/11/2020 5:25 PM



Floor (4/6)  
05/11/2020 5:25 PM




Floor (5/6)  
05/11/2020 5:25 PM




Floor (6/6)  
05/11/2020 5:25 PM



Ceiling (1/4)  
05/11/2020 5:25 PM



Ceiling (2/4)  
05/11/2020 5:25 PM



Ceiling (3/4)  
05/11/2020 5:25 PM



Ceiling (4/4)  
05/11/2020 5:25 PM




Closet / Cupboards / etc (1/9)  
05/11/2020 5:26 PM



Closet / Cupboards / etc (2/9)  
05/11/2020 5:26 PM



Closet / Cupboards / etc (3/9)  
05/11/2020 5:26 PM



Closet / Cupboards / etc (4/9)  
05/11/2020 5:26 PM



Closet / Cupboards / etc (5/9)  
05/11/2020 5:26 PM



Closet / Cupboards / etc (6/9)  
05/11/2020 5:26 PM



Closet / Cupboards / etc (7/9)  
05/11/2020 5:26 PM





Closet / Cupboards / etc (8/9)  
05/11/2020 5:26 PM



Closet / Cupboards / etc (9/9)  
05/11/2020 5:26 PM



Smoke / CO detector  
05/11/2020 5:27 PM

---

## Bedroom 3

| Items                    | Values                        | Notes |
|--------------------------|-------------------------------|-------|
| Door(s)                  | All Good: Yes                 |       |
| Walls / Windows / Blinds | All Good: Yes                 |       |
| Windows Screens          | Condition: Present, no issues |       |
| Floor                    | All Good: Yes                 |       |
| Ceiling                  | All Good: Yes                 |       |
| Smoke / CO detector      | Condition: Present            |       |

## Photos



Overview Photos (1/4)  
05/11/2020 5:27 PM



Overview Photos (2/4)  
05/11/2020 5:27 PM




Overview Photos (3/4)  
05/11/2020 5:27 PM




Overview Photos (4/4)  
05/11/2020 5:27 PM



Door(s) (1/3)  
05/11/2020 5:28 PM



Door(s) (2/3)  
05/11/2020 5:28 PM



Door(s) (3/3)  
05/11/2020 5:28 PM



Walls / Windows / Blinds (1/7)  
05/11/2020 5:28 PM



Walls / Windows / Blinds (2/7)  
05/11/2020 5:28 PM



Walls / Windows / Blinds (3/7)  
05/11/2020 5:28 PM



Walls / Windows / Blinds (4/7)  
05/11/2020 5:28 PM



Walls / Windows / Blinds (5/7)  
05/11/2020 5:28 PM



Walls / Windows / Blinds (6/7)  
05/11/2020 5:28 PM



Walls / Windows / Blinds (7/7)  
05/11/2020 5:28 PM



Floor (1/4)  
05/11/2020 5:29 PM



Floor (2/4)  
05/11/2020 5:29 PM





Floor (3/4)  
05/11/2020 5:29 PM




Floor (4/4)  
05/11/2020 5:29 PM



Ceiling (1/4)  
05/11/2020 5:29 PM



Ceiling (2/4)  
05/11/2020 5:29 PM



Ceiling (3/4)  
05/11/2020 5:29 PM



Ceiling (4/4)  
05/11/2020 5:29 PM



Closet / Cupboards / etc (1/4)  
05/11/2020 5:29 PM



Closet / Cupboards / etc (2/4)  
05/11/2020 5:30 PM



Closet / Cupboards / etc (3/4)  
05/11/2020 5:30 PM



Closet / Cupboards / etc (4/4)  
05/11/2020 5:30 PM



Smoke / CO detector  
05/11/2020 5:30 PM

# Other

| Items                    | Values                        | Notes                                                                       |
|--------------------------|-------------------------------|-----------------------------------------------------------------------------|
| Door(s)                  | All Good: Yes                 |                                                                             |
| Walls / Windows / Blinds | All Good: Yes                 |                                                                             |
| Windows Screens          | Condition: Present, no issues |                                                                             |
| Floor                    | All Good: Yes                 |                                                                             |
| Ceiling                  | All Good: Yes                 |                                                                             |
| Smoke / CO detector      | Condition: Present            |                                                                             |
| Closet / Cupboards / etc | All Good: No                  | Laundry doors don't close at same time. One bifold is always partially open |

## Photos



Overview Photos (1/4)  
05/11/2020 5:17 PM



Overview Photos (2/4)  
05/11/2020 5:18 PM



Overview Photos (3/4)  
05/11/2020 5:18 PM




Overview Photos (4/4)  
05/11/2020 5:18 PM



Door(s) (1/5)  
05/11/2020 5:18 PM



Door(s) (2/5)  
05/11/2020 5:18 PM




Door(s) (3/5)  
05/11/2020 5:18 PM



Door(s) (4/5)  
05/11/2020 5:18 PM



Door(s) (5/5)  
05/11/2020 5:18 PM



Walls / Windows / Blinds (1/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (2/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (3/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (4/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (5/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (6/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (7/15)  
05/11/2020 5:19 PM







Walls / Windows / Blinds (8/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (9/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (10/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (11/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (12/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (13/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (14/15)  
05/11/2020 5:19 PM



Walls / Windows / Blinds (15/15)  
05/11/2020 5:20 PM




Floor (1/4)  
05/11/2020 5:20 PM



Floor (2/4)  
05/11/2020 5:20 PM




Floor (3/4)  
05/11/2020 5:20 PM



Floor (4/4)  
05/11/2020 5:20 PM



Ceiling (1/7)  
05/11/2020 5:20 PM



Ceiling (2/7)  
05/11/2020 5:20 PM




Ceiling (3/7)  
05/11/2020 5:20 PM




Ceiling (4/7)  
05/11/2020 5:20 PM



Ceiling (5/7)  
05/11/2020 5:20 PM



Ceiling (6/7)  
05/11/2020 5:21 PM



Ceiling (7/7)  
05/11/2020 5:21 PM



Smoke / CO detector  
05/11/2020 5:21 PM



Closet / Cupboards / etc (1/7)  
05/11/2020 5:21 PM



Closet / Cupboards / etc (2/7)  
05/11/2020 5:21 PM



Closet / Cupboards / etc (3/7)  
05/11/2020 5:21 PM



Closet / Cupboards / etc (4/7)  
05/11/2020 5:21 PM



Closet / Cupboards / etc (5/7)  
05/11/2020 5:21 PM



Closet / Cupboards / etc (6/7)  
05/11/2020 5:21 PM




Closet / Cupboards / etc (7/7)  
05/11/2020 5:21 PM

## Exterior

| Items             | Values        | Notes                      |
|-------------------|---------------|----------------------------|
| Landscaping       | All Good: Yes | Some patchy spots in grass |
| Building Exterior | All Good: Yes |                            |
| Others            | All Good: Yes |                            |



Photos



Overview Photos (1/9)  
05/11/2020 5:40 PM



Overview Photos (2/9)  
05/11/2020 5:40 PM



Overview Photos (3/9)  
05/11/2020 5:40 PM



Overview Photos (4/9)  
05/11/2020 5:40 PM



Overview Photos (5/9)  
05/11/2020 5:40 PM



Overview Photos (6/9)  
05/11/2020 5:49 PM



Overview Photos (7/9)  
05/11/2020 5:49 PM



Overview Photos (8/9)  
05/11/2020 5:49 PM



Overview Photos (9/9)  
05/11/2020 5:50 PM



Landscaping (1/8)  
05/11/2020 5:41 PM



Landscaping (2/8)  
05/11/2020 5:41 PM



Landscaping (3/8)  
05/11/2020 5:41 PM



Landscaping (4/8)  
05/11/2020 5:41 PM



Landscaping (5/8)  
05/11/2020 5:50 PM



Landscaping (6/8)  
05/11/2020 5:50 PM



Landscaping (7/8)  
05/11/2020 5:50 PM





Landscaping (8/8)  
05/11/2020 5:50 PM



Building Exterior (1/11)  
05/11/2020 5:41 PM



Building Exterior (2/11)  
05/11/2020 5:41 PM



Building Exterior (3/11)  
05/11/2020 5:41 PM



Building Exterior (4/11)  
05/11/2020 5:42 PM



Building Exterior (5/11)  
05/11/2020 5:42 PM



Building Exterior (6/11)  
05/11/2020 5:42 PM



Building Exterior (7/11)  
05/11/2020 5:51 PM



Building Exterior (8/11)  
05/11/2020 5:51 PM



Building Exterior (9/11)  
05/11/2020 5:51 PM



Building Exterior (10/11)  
05/11/2020 5:51 PM



Building Exterior (11/11)  
05/11/2020 5:51 PM



Others (1/4)  
05/11/2020 5:42 PM



Others (2/4)  
05/11/2020 5:42 PM



Others (3/4)  
05/11/2020 5:42 PM



Others (4/4)  
05/11/2020 5:42 PM

# Odors/Cleanliness/Comments

| Items             | Values                                                          | Notes                             |
|-------------------|-----------------------------------------------------------------|-----------------------------------|
| Comments on Odors | No out of ordinary smells: Something does smell out of ordinary | Very slight cat/pet odor upstairs |



| Items                | Values           | Notes                                                   |
|----------------------|------------------|---------------------------------------------------------|
| Property Cleanliness | Condition: Clean | Walls and baseboards dirty but everything else is clean |

## Other 2

| Items                    | Values                 | Notes |
|--------------------------|------------------------|-------|
| Door(s)                  | All Good: Yes          |       |
| Walls / Windows / Blinds | All Good: Yes          |       |
| Floor                    | All Good: Yes          |       |
| Ceiling                  | All Good: Yes          |       |
| Smoke / CO detector      | Condition: Not present |       |
| Other / Room Specific    | All Good: Yes          |       |


## Photos



Overview Photos (1/4)  
05/11/2020 5:44 PM



Overview Photos (2/4)  
05/11/2020 5:44 PM



Overview Photos (3/4)  
05/11/2020 5:44 PM



Overview Photos (4/4)  
05/11/2020 5:44 PM



Door(s) (1/3)  
05/11/2020 5:45 PM



Door(s) (2/3)  
05/11/2020 5:45 PM



Door(s) (3/3)  
05/11/2020 5:45 PM



Walls / Windows / Blinds (1/5)  
05/11/2020 5:45 PM



Walls / Windows / Blinds (2/5)  
05/11/2020 5:45 PM



Walls / Windows / Blinds (3/5)  
05/11/2020 5:45 PM



Walls / Windows / Blinds (4/5)  
05/11/2020 5:45 PM



Walls / Windows / Blinds (5/5)  
05/11/2020 5:45 PM



Floor (1/4)  
05/11/2020 5:45 PM



Floor (2/4)  
05/11/2020 5:46 PM



Floor (3/4)  
05/11/2020 5:46 PM



Floor (4/4)  
05/11/2020 5:46 PM



Ceiling (1/4)  
05/11/2020 5:46 PM



Ceiling (2/4)  
05/11/2020 5:46 PM



Ceiling (3/4)  
05/11/2020 5:46 PM



Ceiling (4/4)  
05/11/2020 5:46 PM



Other / Room Specific  
05/11/2020 5:46 PM